


Speed Probe / Sensor Types

Wire connections to the müller speedometer



Probe Square Pin

Positive (+) → Speedo PIN no 16 (red)

Negative (-) → Speedo PIN no 17 (black)

Pulse \square → Speedo PIN no 18 (blue)



Probe Round Pin

PIN 1 (+) → Speedo PIN no 16 (red)

PIN 2 (-) → Speedo PIN no 17 (black)

PIN 3 \square → Speedo PIN no 18 (blue)



Mechanical Speed Sensor

Sensor Brown (+) → Speedo PIN no 16 (red)

Sensor Yellow/Green (-) → Speedo PIN no 17 (black)

Sensor Blue or Black \square → Speedo PIN no 18 (blue)



GPS Speed Sensor – Calibration 5000 pulses/km

Sensor Red (+) → Vehicle Permanent (+)

Sensor Black (-) → Vehicle Ground (-)

Sensor Blue \square → Speedo PIN no 18 (blue)

Sensor Green → Aux pulse

The GPS Antenna must be mounted in such a way that it can “see” the sky, i.e. no metal surface must be above it; plastic is ok.

GPS NOT Found - LED RED. GPS Found - LED GREEN.